

11/09/2012

Discontinued Product

Dear Sir or Madam,

In the course of continuous improvement of our product quality, reliability and up to date technology we decided to discontinue the following product.

Here you will find the relevant product information:

Discontinued Product:	PSM 25 to 86; Article/Id No: 10004141, 10004142, 10004143, 10004144, 10004145, 10010247, 10004146, 10004147, 10004148, 10004149, 10010245, 10010246
Reason for discontinuation	End of product lifetime
Date of discontinuation	October 31, 2012
Repair & Service until	- - -
Suggested replacement	- - -
Last call	Your order before October 31, 2012 (The delivery is from Dec 2012)

We look forward to supporting you finding the right follow-on product for your application.

Feel free to call or send an email to:

Mr. Wahid Lahmadi

T +1.802.872.1600

E info@phytron.com

Phytron, Inc.

Phytron, Inc.

600 Blair Park Road, Suite 220, Williston, VT 05495, USA

Tel.: +1.802.872.1600

Fax: +1.802.872.0311

Mail: info@phytron.com

Web: www.phytron.com